



Ministry of the
Environment

Ontario

Site Inspection Report

FILE No.
A-210102

DATE
Jan 4, 1978

Re: Burlington Landfill, Lot 4, Concession 1 & 2, City of Burlington

On December 15, 1977 the above waste disposal site was inspected by

H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	-	-

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site 2) Adjacent Property	X X	
14. Working Face	X	
15. Number of Dumping Areas		X
16. Segregation of Refuse		X
17. Segregated Material Disposal		X
18. Rodent and Vector Control	-	-
19. Means of Controlling Litter	-	-

Operation Discussed with _____ (NAME) _____ (POSITION)

COMMENTS

- Working face located ~~80~~ in south half of the site adjacent and the old roadway.
- 15 & 16 & 17. A wood waste area has been established to the west of the weigh scale station. Noted assorted wood wastes. In addition, refuse is being thrown into this area also. Thus refuse does not get covered on a daily basis.
- No new work has been done on the leachate collector system. There is apparently a problem with obtaining an easement through private property for the sewer line.
- Snow cover on site during inspection.

RECOMMENDATIONS

1. Wood wastes to be dumped into the daily working face.
2. Leachate collector system to be completed as soon as possible.

Disposal area is reaching contours at a rapid rate.

APPROVED BY

DISTRICT OFFICER