

W-11-02
BURLINGTON
A 210102

1982 04 29

Mr. D.J. Corbett, P. Eng.
Manager - Construction
Regional Municipality of Halton
P.O. Box 7000
1151 Bronte Road
Oakville, Ontario
L6J 6E1


Dear Mr. Corbett:

RE: Region of Halton Landfill Sites -
Georgetown, Oakville, Burlington

Attached are recent site inspection reports made by Mr. H. Paar
of this office. Please note the comments contained in this
report.

If there are any enquiries regarding the contents of these reports,
please do not hesitate to contact this office.

Yours truly,



G.L. McCarty, P. Eng.
Sr. Environmental Officer
Municipal and Private Abatement Section

GLM/yf
Attached



Ministry
of the
Environment
Ontario

Waste Disposal Site Inspection Form

FILE No.
A21010A

DATE
April 29, 1982

Re: Burlington Landfill, Lot 4, Concession 1 and 2, City of Burlington

On April 15, 1982 the above waste disposal site was inspected by
H. Paar when the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
Scavenging		X
10. Operating According to Conditions on Certificate of Approval	X	

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site		X
2) Adjacent Property		X
14. Working Face	X	
15. Number of Dumping Areas	-	-
16. Segregation of Refuse	-	-
17. Segregated Material Disposal	-	-
18. Rodent and Vector Control	-	-
19. Means of Controlling Litter	-	-

Operation Discussed with Mr. S. Mucciarrellie
(NAME)

Region of Halton
(POSITION)

COMMENTS

- Site operations and development discussed with Mr. Mucciarrellie.
- Landfilling operations are continuing in the Phase I expansion area.
- 13. (1) & (2) Litter noted along the east side of the site. This litter was in the processes of being cleaned up by a 4 men crew.
- Waste disposal operations satisfactory.
- Leachate flows are now being measured and recorded. Flows currently measure about 50 I.G.P.M. (Some of this is from surface water in the Phase II expansion area).
- The leachate underdrain and toe-drain is being installed in the Phase II expansion area. Four underdrain lines are currently being installed and also the west side toe-drain. One of the underdrain lines (2nd) has been installed with a filter cloth material (Terrafix 270R). Project installation briefly discussed with Mr. J. Williams of Dillon.
- The container area for small vehicles is being prepared on the west side of the scale house-equipment building.

RECOMMENDATIONS