


San Juan Co., N.M., Nov. 17, '84


1. South side
Furnace
crucible
garbage



2. South side
Furnace detail




3. South side
Another detail
incl. location



Bayview Park, Nov. 17, '84

4. Garbage
exposed
by furrow
(South rink)




(#5 divider
+ #3)

6. South rink
grade below
original grade
of cap
(stop at fence)




7. Erosion
at SW corner
of South rink




Bayview Park, Nov. 17 '84

8. North riuk
water infiltration
shown by water level
below night's ice cover
(Time approx. 10³⁰-11⁰⁰ am)



9. South edge
of Bayview -
leaves & slash
dumped there
(facing North)



10. (as 9.)
(facing East)




Rayview Park, Nov. 17, '64

11. Landfill cap, Y junction
of roads: Erosion/garbage



13. (As 11.), North of road junction




12. Erosion at Y junction of roads.
Note stony soil (infiltration)



Bayview Park, Nov. 17. '84

14. Forlorne "NO DUMPING" sign at Y of roads



15. Road entrance (well used) is wide open
- from King Rd., N. of rifle range (not for rinks).

