SM

the metropolitan toronto and region conservation authority
5 shoreham drive, downsview, ontario, m3n 1s4 (416) 661-6600 FAX 661-6898

IMPROVED LAKEFILL QUALITY CONTROL PROGRAM

MONTHLY REPORT

JANUARY 1991

Contents

I Introduction.....Page 1

II Discussion.....Page 1

III Fill Received Statistics.....Page 1

IV Rejected Material.....Page 2

V Chemical Test Audit Results.....Page 2-3

VI Site by Site Breakdown of Fill Volumes.....Page 3

VII Appendix A - Lakefill Location Soil Acceptability Checklists

VIII Appendix B - Violation Reports

contains recycled material

I Introduction

The following report contains the fill received statistics for all lakefill sites in the month of January 1991.

II Discussion

The volume of fill received at lakefill sites in January, 1991, was once again down significantly from the same month the previous year. The number of truck loads of lakefilled soils in January 1990 was 11,282 as compared to 1,374 in January 1991.

The slow lakefilling activity was reflected in many other ways in January. The ILQCP staff received only eleven applications for lakefill Bills of Lading all of which were approved in full with no material rejected. In addition, no violations were uncovered in January.

III Fill Received Statistics

Table 1. Destination Area Breakdown for January, 1991.

	Volume (m^3)		
	Open Water	Protected	Confined
Large Projects	13,500	0	60
Small Projects	0	0	180

Table 2. Fill Volume Totals for January, 1991.

	Volume(m^3)	% of Total
Large Projects	13,560	98.6
Small Projects	180	1.4
Total	13,740	100.0

IV Rejected Material

A. Material rejected at the application stage by chemical analysis results.

- No soil was rejected in this manner in January 1991.

B. Material rejected after visual inspection of excavation sites. These projects were all rejected in their entirety.

- No soil was rejected in this manner in January 1991.

C. Truck loads rejected by visual inspection at the lakefill site .

- No truck loads were rejected in this manner in January, 1991.

V Chemical Testing Audit Results

Table 3. Summary of Test Results Obtained as part of the I.L.Q.C.P. internal auditing program in January, 1991.

Type of Sample	# of Results Received	# Failing Open Water Guidelines	# Failing Restricted Guidelines
Taken from trucks originating from "small projects"	0	-	-
Taken from trucks originating from "large projects"	3	0	0

Results Discussion

All samples taken tested below the Open Water Guidelines.

VI Fill Volumes Received by Site

Table 4. Site by Site Breakdown of Fill Volumes Received in January 1991.

Site	Volume (cubic metres) Open Water	Protected	Confined
Leslie St.	11,370	0	0
Sam Smith	2,130	0	240
Fishleigh	0	0	0
Guildwood	0	0	0
Bellamy	0	0	0
Totals	13,500	0	240

VII Appendix A

Lakefill Location Soil Acceptability Checklists

Note: No reports issued in January 1991.

VIII Appendix B

Violation Reports

Note : No violation reports were issued in January 1991.