

1982 01 22

Mr. R.W.J. Moore, P. Eng.
Director of Public Works
Regional Municipality of Halton
P.O. Box 7000
1151 Bronte Road
Oakville, Ontario
L6J 6E1


Dear Mr. Moore:

Re: Regional Municipality of Halton
Burlington Landfill Site A 210102
Our File: WM 11-02

The approval of the leachate collection system and transmission sewer at the Burlington landfill was in part conditioned upon a monitoring program being implemented for measuring and recording the quantity and quality of leachate being discharged into the sewer collection system for ultimate treatment at the Skyway Water Pollution Control Plant. It is our understanding that leachate flows to date have not been measured nor recorded.

We would request that you advise this office of the reasons for delays that have occurred and immediate actions to be taken for the necessary measurement and recording of the leachate flows.

Yours truly,



K.S. Hogg, P. Eng.
District Officer
Municipal & Private Abatement Section
HP/ns/Pl-V