

Re: Sanitary Landfill Waste Disposal Site, Concession 1 and 2.

On February 21, 1974 the above waste disposal site was inspected by

P. S. Isles

of the Waste Management Branch when the following observations were made:

	YES	NO
1. Site Open	☒	
2. Refuse being deposited at time of inspection	☒	
3. Access Controlled	☒	
4. Site Supervised	☒	
5. Adequate Signs Posted	☒	
6. Site open in accordance with posted signs	☒	
7. Covering Equipment on Site	☒	
8. Burning		☒
9. Scavenging		☒
10. Operating According to Conditions on Certificate of Approval		

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	☒	
12. Cover of Refuse		☒
13. Housekeeping of 1) Site 2) Adjacent Property	☒	☒
14. Working Face	☒	
15. Number of Dumping Areas	☒	
16. Segregation of Refuse	☒	
17. Segregated Material Disposal	☒	
18. Rodent and Vector Control		
19. Means of Controlling Litter		

Operation Discussed with _____ (NAME) _____ (POSITION)

COMMENTS

At the time of the inspection an area away from the working face was only partially covered.

RECOMMENDATIONS

That the above mentioned area be adequately covered.

PREPARED BY P. S. Isles

APPROVED BY [Signature]

Regional Engineer



Ontario

A 210231
DATE
April 23, 1974Re: Town of Burlington Waste Disposal Site, Concession 1 and 2On April 22, 1974 the above waste disposal site was inspected byH. Paar of the Waste Management Branch when the following observations were made:

	YES	NO		SATIS- FACTORY	UNSATIS- FACTORY
1. Site Open	☒		11. Compaction of Refuse	☒	
2. Refuse being deposited at time of inspection	☒		12. Cover of Refuse	☒	
3. Access Controlled	☒		13. Housekeeping of 1) Site	☒	
4. Site Supervised	☒		2) Adjacent Property	☒	
5. Adequate Signs Posted	☒		14. Working Face	☒	
6. Site open in accordance with posted signs	☒		15. Number of Dumping Areas	☒	
7. Covering Equipment on Site	☒		16. Segregation of Refuse		
8. Burning		☒	17. Segregated Material Disposal		
9. Scavenging		☒	18. Rodent and Vector Control		
10. Operating According to Conditions on Certificate of Approval			19. Means of Controlling Litter		

Operation Discussed with Bill Menary Supervisor
(NAME) (POSITION)

COMMENTS

5. Sign indicating operating hours has fallen down due to breakage of support posts.

RECOMMENDATIONS

Sign indicating operating hours be re-erected at the entrance to the site.

PREPARED BY

H. Paar

APPROVED BY

Regional Engineer

WASTE MANAGEMENT BRANCH

A 210201

DATE

May 23, 1974.

Ontario

Re: Burlington Waste Disposal Site, Concession 1 & 2,

On May 22, 1974 the above waste disposal site was inspected by

H. Paar

of the Waste Management Branch when the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval		

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse		X
12. Cover of Refuse		X
13. Housekeeping of 1) Site		X
2) Adjacent Property	X	
14. Working Face		X
15. Number of Dumping Areas	X	
16. Segregation of Refuse		
17. Segregated Material Disposal		
18. Rodent and Vector Control		
19. Means of Controlling Litter		

Operation Discussed with

(NAME)

(POSITION)

COMMENTS

- Two working faces in operation.
- The working face at the north end of the property too large and deep.
- Some litter scattered along the east and west sides of the disposal site.
- Access road dusty.
- Some refuse has been dumped outside the waste disposal site at the entrance.

RECOMMENDATIONS

- Refuse outside the gates to be removed.

PREPARED BY H. Paar

APPROVED BY

Regional Engineer



Ontario

MINISTRY OF THE ENVIRONMENT
WASTE MANAGEMENT BRANCH
MUNICIPAL & PRIVATE ABATEMENT

Mr. D.R. Morrier

Reg. Mun. of Halton
3027 Harvester Road
Burlington, Ontario

FILE No.
A - 210102
DATE
August 12, 1974

Re: Burlington W.D.S., Part Lot 4, Conc. 1 & 2, City of Burlington

On August 1, 1974

the above waste disposal site was inspected by

H. Paar

Toronto District Office
of the Waste Management Branch when the following

observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	---	---

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site	X	
2) Adjacent Property	X	
14. Working Face	X	
15. Number of Dumping Areas	---	---
16. Segregation of Refuse	---	---
17. Segregated Material Disposal	---	---
18. Rodent and Vector Control	---	---
19. Means of Controlling Litter	---	---

Operation Discussed with

(NAME)

(POSITION)

COMMENTS

Working face located near the north boundary. A new road has been constructed to the working face area. This road runs generally along the west side of the site. The on-site road has been recently oiled to control dust.

RECOMMENDATIONS

PREPARED BY

H. Paar

APPROVED BY

Regional Engineer



Ontario

Ministry of the
Environment

Waste Management Branch

Morrison

Regional Municipality of Halton

3027 Harvester Rd.

Burlington, Ont. L7N 3G8

Site Inspection Form

FILE No.

A-210102

DATE

Re: Burlington W.D.S., Lot 4, Concession 1 & 2, City of Burlington

On November 15, 1974 the above waste disposal site was inspected by

H. Paar

of the Toronto District Office
Waste Management Branch when the following

observations were made:

	YES	NO		SATIS- FACTORY	UNSATIS- FACTORY
1. Site Open	X		11. Compaction of Refuse	X	
2. Refuse being deposited at time of inspection	X		12. Cover of Refuse	X	
3. Access Controlled	X		13. Housekeeping of 1) Site		X
4. Site Supervised	X		2) Adjacent Property	X	
5. Adequate Signs Posted	X		14. Working Face	X	
6. Site open in accordance with posted signs	X		15. Number of Dumping Areas		
7. Covering Equipment on Site	X		16. Segregation of Refuse		
8. Burning		X	17. Segregated Material Disposal		
9. Scavenging		X	18. Rodent and Vector Control		
10. Operating According to Conditions on Certificate of Approval			19. Means of Controlling Litter		

Operation Discussed with Mr. B. Menary

(NAME)

(POSITION)

COMMENTS

13. Litter on site around working face area. (High winds present during site inspection.)

RECOMMENDATIONS

PREPARED BY

H. Paar

APPROVED BY

[Signature]
Regional Engineer



Ontario

Ministry of the
Environment

D. MORRIS
Regional Municipality of Halton
302 Harvester Road
Burlington, Ontario, L7N 3G8

Site Inspection Report

FILE No.
A-210102

DATE

Burlington W.D.S., Lot 4, Conc. 1 & 2, City of Burlington

Re: _____
On January 7, 1975 the above waste disposal site was inspected by

H. Paar

of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	x	
2. Refuse being deposited at time of inspection	x	
3. Access Controlled	x	
4. Site Supervised	x	
5. Adequate Signs Posted	x	
6. Site open in accordance with posted signs	x	
7. Covering Equipment on Site	x	
8. Burning		x
9. Scavenging		x
Operating According to Conditions on Certificate of Approval	-	-

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	x	
12. Cover of Refuse	x	
13. Housekeeping of 1) Site		x
2) Adjacent Property	x	
14. Working Face	x	
15. Number of Dumping Areas	-	-
16. Segregation of Refuse	-	-
17. Segregated Material Disposal	-	-
18. Rodent and Vector Control	-	-
19. Means of Controlling Litter	-	-

Operation Discussed with _____ (NAME) _____ (POSITION)

COMMENTS

13. Some litter to the east of the working face

Note: Refuse has been dumped just outside the main gates into the site

RECOMMENDATIONS

PREPARED BY

H. Paar

APPROVED BY

DISTRICT OFFICER



Ontario

Ministry of the
Environment

D.R. MORRIS

Manager, Operations & Maintenance
Public Works Dept. Site Inspection Report

3027 Harvester Road,
Burlington, Ontario L7N 3G8.

FILE No. A - 210102

DATE
MARCH 20 1975

Re: BURLINGTON W.D.S., LOT 4; CONC. 1 & 2, CITY OF BURLINGTON.

On MARCH 18, 1975.

the above waste disposal site was inspected by

H. PAAR & A.D. SAUNDERS

TORONTO DISTRICT OFFICE.

of the

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	---	---

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site 2) Adjacent Property	X	X
14. Working Face	X	
15. Number of Dumping Areas	---	---
16. Segregation of Refuse	---	---
17. Segregated Material Disposal	---	---
18. Rodent and Vector Control	---	---
19. Means of Controlling Litter	---	---

Operation Discussed with

(NAME)

(POSITION)

COMMENTS

- Operation satisfactory.
- Some refuse dumped just outside the entrance gates.

13. Noted some litter along the east side near the working face. Litter was being picked up during site inspection.

RECOMMENDATIONS

PREPARED BY

APPROVED BY

DISTRICT OFFICER



Ontario

Ministry of the
Environment

Mr. D. Morfier, Manager
Operations & Maintenance,
Public Works Dept. Site Inspection Report
Regional Municipality of Halton,
3027 Harvester Road, Burlington, Ont. L7N 3G8

FILE No.	A-210102
DATE	May 6, 1975

Re: Burlington W.D.S., Lot 9, Concession 1 & 2, City of Burlington

On May 2, 1975 the above waste disposal site was inspected by

H. Paar

of the Toronto District Office

at which time the following observations were made:

	YES	NO		SATIS- FACTORY	UNSATIS- FACTORY
1. Site Open	X		11. Compaction of Refuse	X	
2. Refuse being deposited at time of inspection	X		12. Cover of Refuse	X	
3. Access Controlled	X		13. Housekeeping of 1) Site		X
4. Site Supervised	X		2) Adjacent Property		X
5. Adequate Signs Posted	X		14. Working Face	X	
6. Site open in accordance with posted signs	X		15. Number of Dumping Areas	---	---
7. Covering Equipment on Site	X		16. Segregation of Refuse	---	---
8. Burning		X	17. Segregated Material Disposal	---	---
9. Scavenging		X	18. Rodent and Vector Control	---	---
Operating According to Conditions on Certificate of Approval	---	---	19. Means of Controlling Litter	---	---

Operation Discussed with Mr. H. Peters (NAME) Environmental Quality Handling Ltd. (POSITION)

COMMENTS May 1, 1975 new site operators - Environmental Quality Handling Ltd.

13 (1) Site requires a good clean up and grading program.

13 (2) Refuse still being dumped outside the main entrance area.

Note: Operation proposal by Environmental Quality Handling Ltd.
Lifts with cell operation. Rubble and stumps only in a
segregated area.

RECOMMENDATIONS

Illegal dumping at the main entrance area to be
controlled.

Litter cleanup and site grading required.

PREPARED BY

H. PAAR

APPROVED BY

DISTRICT OFFICER



Ministry of the
Environment

Ontario

Site Inspection Report

FILE No.
A 210102

DATE
May 23, 1975

Re: Burlington W.D.S., Lot 4, Concession 1 & 2, City of Burlington

On May 14, 1975 the above waste disposal site was inspected by

H. Paar, P. Isles & A. Giffen of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	----	----

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site		X
2) Adjacent Property	X	
14. Working Face	X	
15. Number of Dumping Areas	X	
16. Segregation of Refuse	X	
17. Segregated Material Disposal	-----	-----
18. Rodent and Vector Control	-----	-----
19. Means of Controlling Litter	-----	-----

Operation Discussed with _____

(NAME)

(POSITION)

COMMENTS

Two operating areas: 1. Rubble, branches & stumps
2. Domestic, industrial wastes

13(1) Site still needs a continued clean up. Some improvements noted.

NOTED: A container outside gates for waste control.

RECOMMENDATIONS

PREPARED BY

H. PAAR

APPROVED BY

DISTRICT OFFICER



Ministry of the
Environment

Ontario

Site Inspection Report

FILE No.

A 210102

DATE

July 9, 1975

Re: Burlington W.D.S., Lot 4, Concession 1 and 2, City of Burlington

On June 19, 1975 the above waste disposal site was inspected by

H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
Operating According to Conditions on Certificate of Approval	----	----

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse		X
13. Housekeeping of 1) Site 2) Adjacent Property	X	X
14. Working Face	X	
15. Number of Dumping Areas	X	
16. Segregation of Refuse	X	
17. Segregated Material Disposal	X	
18. Rodent and Vector Control	----	----
19. Means of Controlling Litter	----	----

Operation Discussed with _____
(NAME) (POSITION)

COMMENTS

- Working face located on top at the back of the property
Brush and rubble being dumped into the depression on the top near the on-site road.
- Additional soil cover required in filled areas, especially in the pocket near the telephone lines.

RECOMMENDATIONS

Soil cover operations must completely cover wastes.

Refuse dumping outside the main entrance to be cleaned up.

PREPARED BY H. Paar

APPROVED BY [Signature]

DISTRICT OFFICER



Ministry of the
Environment

Ontario

D. Morrier, Manager
Operations & Maintenance
Regional Municipality
of Halton,
3027 Harvester Road, Burlington, Ont.

Site Inspection Report

FILE No.	A - 210102
DATE	July 31, 1975

Re: Burlington W.D.S., Lot 4, Concession 1 & 2, City of Burlington

On July 29, 1975 the above waste disposal site was inspected by
H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval		

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site 2) Adjacent Property	X	X
14. Working Face	X	
15. Number of Dumping Areas	X	
16. Segregation of Refuse	X	
17. Segregated Material Disposal	X	
18. Rodent and Vector Control		
19. Means of Controlling Litter		

Operation Discussed with Mr. N. MacDuff Site Supervisor (Environmental Quality
(NAME) (POSITION) Handling Lt.)

COMMENTS

- Working face adjacent to the on-site road at the bottom near the overhead telephone lines.
- Rubble and limited brush dumping from the top.
- 13. Incredible mess just outside the main gates at the turning circle. It appears uncontrolled dumping is being carried on in this area. Noted wastes covering a area 50' x 20' x 3'. Also scattered wastes in this area.

COMMENDATIONS

Refuse dumping outside the main entrance to be cleaned up and controlled.

PREPARED BY

H. Paar

APPROVED BY

DISTRICT OFFICER



Ministry of the
Environment

Ontario

Site Inspection Report

FILE No.	S A 210102
DATE	September 5/75

Re: Burlington W.D.S., Lot 4, Con.1 & 2, City of Burlington

On August 26, 1975 the above waste disposal site was inspected by
H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	--	--

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site 2) Adjacent Property	X	X
14. Working Face	X	
15. Number of Dumping Areas	--	--
16. Segregation of Refuse	--	--
17. Segregated Material Disposal	--	--
18. Rodent and Vector Control	--	--
19. Means of Controlling Litter	--	--

Operation Discussed with Mr. N. MacDuff
(NAME)

Site Supervisor
(POSITION)

COMMENTS

- 13(2) - Dumping of wastes still occurring outside main entrance. Noted a loader-backhoe add truck cleaning up wastes at the entrance.
- Working face located around the telephone lines cutting the property. Dumping operations from the top road on the west side.
 - In the area of the dumping face, a drainage problem was noted.

RECOMMENDATIONS

Dumping outside the main entrance gates must be controlled.

PREPARED BY <u>H. Paar</u>	APPROVED BY <u>[Signature]</u>	DISTRICT OFFICER
-------------------------------	-----------------------------------	------------------



Re: Burlington W.D.S. Lot 4, Concession 1 & 2, City of Burlington

On September 26, 1975 the above waste disposal site was inspected by

H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	-	-

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse		X
13. Housekeeping of 1) Site 2) Adjacent Property	X	X
14. Working Face	X	
15. Number of Dumping Areas	X	
16. Segregation of Refuse	X	
17. Segregated Material Disposal	X	
18. Rodent and Vector Control	-	-
19. Means of Controlling Litter	-	-

Operation Discussed with _____

(NAME)

(POSITION)

COMMENTS

- Working face off the top of the on-site road on the west side.
- Brush, stumps and concrete dumped into the ravine edge on the east side.
- 13(a) Entrance area is not adequately controlled for illegal dumping. Considerable wastes noted in ditches at the entrance area.
- 12. Some additional cover material required in and around the low area at the hydro lines. Weather and ground conditions were not favourable for covering operations during site visits i.e. rain, mud.

RECOMMENDATIONS

1. Illegal dumping at the entrance area to be controlled.
2. Additional cover to be applied in areas of exposed refuse.

PREPARED BY

H. Paar

APPROVED BY

DISTRICT OFFICER

Ontario

Re: Burlington Waste Disposal Site, Lot 4, Concession 1 & 2, City of Burlington

On February 3, 1976 the above waste disposal site was inspected by

H. Paar

of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Ravenging		X
10. Operating According to Conditions on Certificate of Approval	--	--

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site		X
2) Adjacent Property		X
14. Working Face	X	
15. Number of Dumping Areas	--	--
16. Segregation of Refuse	--	--
17. Segregated Material Disposal	--	--
18. Rodent and Vector Control	--	--
19. Means of Controlling Litter	--	--

Operation Discussed with _____ (NAME) _____ (POSITION)

COMMENTS

- Working face located in the trench on the west side on the on-site road. Trench is located in the south half of the side of the site, to the north west of the weigh scale station.
 - Some exposed waste located in the filled area around the telephone and hydro lines cutting through the property.
- 13 (1) (2) - Some litter noted on the east side on the on-site road and toward the adjacent property on the east side.

RECOMMENDATIONS

- Litter to be cleaned up.
- Waste projecting through in the area of the telephone - hydro lines to be covered with additional soil once weather and ground conditions permit.

PREPARED BY

H. Parr

APPROVED BY

DISTRICT OFFICER

Re: Burlington W.D.S., Lot 4, Concession 1 & 2, City of Burlington

On March 30, 1976 the above waste disposal site was inspected by
H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. scavenging		X
10. Operating According to Conditions on Certificate of Approval		

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse		X
13. Housekeeping of 1) Site 2) Adjacent Property	X X	
14. Working Face	X	
15. Number of Dumping Areas	X	
16. Segregation of Refuse	X	
17. Segregated Material Disposal	X	
18. Rodent and Vector Control		
19. Means of Controlling Litter		

Operation Discussed with Mr. K. Ramsahai Technical Services Eng.-Halton Region
(NAME) (POSITION)

COMMENTS

Working face on the west side of the on-site road past the weigh scale station. When operations move to the back of the property an interim soil cover together with grading should be done in this area.

Some segregation of Wood products and concrete noted in the area of the excavation to the west of the weigh scale station and near the hydro lines on the east boundary in a depression area.

12. Grading and covering has ^{to be} improved in the area where the telephone lines cut through the property.

NOTED: Leachate along the east side, originating from the depression area of segregated refuse. Similarly evidence of some leachate noted on the south side of the site.

RECOMMENDATIONS

Leachate sub-drain to be installed and leachate collected for disposal.

As discussed with Mr. K. Ramsahai, the proposed location for dry waste products will receive our comments upon the request by the Region to extend the disposal operations outside the present approved areas. Therefore, should the Region pursue this matter, written notification is required accompanied with a location map.

PREPARED BY <u>H. Paar</u>	APPROVED BY <u>[Signature]</u>	DISTRICT OFFICER <u>[Signature]</u>
-------------------------------	-----------------------------------	--

Arlington W.D.S. , Lot 4, Concession 1 & 2, City of Burlington

On July 27, 1976 the above waste disposal site was inspected by

H. Paar of the Toronto District Office

at which time the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
Scavenging		X
10. Operating According to Conditions on Certificate of Approval	-	-

	SATIS-FACTORY	UNSATIS-FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site	X	
2) Adjacent Property	X	
14. Working Face	X	
15. Number of Dumping Areas	-	-
16. Segregation of Refuse	-	-
17. Segregated Material Disposal	-	-
18. Rodent and Vector Control	-	-
19. Means of Controlling Litter	-	-

Operation Discussed with

(NAME)

(POSITION)

COMMENTS

- Working face located at the north end of the property in the first trench.
- Operations satisfactory.
- Refuse still being dumped outside the main entrance area around the turning circle.
- Leachate discharge still noted.

RECOMMENDATIONS

- Waste disposal outside gates still not being adequately controlled. Therefore, action is required to control dumping in this area.
- Leachate control required.
- In our letter of May 31, 1976, we requested action to be taken by the Region on leachate control. A reply on this request is still outstanding.

PREPARED BY

H. Paar

APPROVED BY

DISTRICT OFFICER