

FILE WM-11-02

A 210102

E.I.
G.M.C.
H.P.

1983 02 07

Mr. D.J. Corbett
Waste Disposal Engineer
Public Works Department
Regional Municipality of Halton
P.O. Box 7000
1151 Bronte Road
Oakville, Ontario
L6J 6E1


Dear Mr. Corbett:

Re: Region of Halton Landfill Site
Burlington-North Service Road

Attached is a recent site inspection report made by Mr. H. Paar of this office. Please note the comments contained in the report.

If there are any enquiries regarding the contents of the report, please do not hesitate to contact this office.

Yours very truly,



G.L. McCarty, P.Eng.
Sr. Environmental Officer
Municipal and Private Abatement section

Attach:
HP:cra:M1-H



Ontario

Ministry
of the
Environment

Waste Disposal Site Inspection Form

FILE No.

A210102

DATE

January 24, 1983

Re: Burlington Landfill, Lot 4, Concession 1 & 2, City of BurlingtonOn January 18, 1983 the above waste disposal site was inspected byH. Paar when the following observations were made:

	YES	NO
1. Site Open	X	
2. Refuse being deposited at time of inspection	X	
3. Access Controlled	X	
4. Site Supervised	X	
5. Adequate Signs Posted	X	
6. Site open in accordance with posted signs	X	
7. Covering Equipment on Site	X	
8. Burning		X
9. Scavenging		X
10. Operating According to Conditions on Certificate of Approval	X	

	SATIS- FACTORY	UNSATIS- FACTORY
11. Compaction of Refuse	X	
12. Cover of Refuse	X	
13. Housekeeping of 1) Site		X
2) Adjacent Property	X	
14. Working Face	X	
15. Number of Dumping Areas	--	--
16. Segregation of Refuse	--	--
17. Segregated Material Disposal	--	--
18. Rodent and Vector Control	--	--
19. Means of Controlling Litter	--	--

Operation Discussed with _____
(NAME) (POSITION)

COMMENTS

- Landfilling operations are located in the south half of the Phase II expansion area.
- During the site visit extreme winds were blowing from a northerly direction. These winds resulted in litter being blown away from the working face, over the litter fence and down toward the south boundary of the site
- New electronic weigh scales (inbound and outbound) have been installed and are operational at the former site entrance area.
- Container area for small vehicles, private automobiles, is operational. An attendant at the entrance to the container area directs appropriate traffic to the open containers.
- The new equipment building in the Phase II expansion area is also in use.
- Siltation pond adjacent to the North Service Road has been enclosed by a chain link fence.
- New signs have been posted indicating site use, fees, operating hours, etc.

RECOMMENDATIONS

- The container for newspaper recycling has been moved to an area in front of the weigh scale station on the east side of the access road.